



10/773880

Colc



# BLAKELY SOKOLOFF TAYLOR & ZAFMAN

A LIMITED LIABILITY PARTNERSHIP INCLUDING LAW CORPORATIONS



TELEPHONE (408) 720-8300

FACSIMILE (408) 720-8383

BSTZ\_MAIL@BSTZ.COM

WWW.BSTZ.COM

INTELLECTUAL PROPERTY LAW

SILICON VALLEY

1279 OAKMEAD PARKWAY  
SUNNYVALE, CALIFORNIA 94085-4040

OTHER OFFICES

LOS ANGELES, CA  
ORANGE COUNTY/COSTA MESA, CA  
SAN JOSE, CA  
DENVER, CO  
PORTLAND/BEAVERTON, OR  
SEATTLE, WA

November 29, 2005

Commissioner for Patents  
PO Box 1450  
Alexandria, VA 22313-1450

Re: **CERTIFICATE OF CORRECTION**  
U. S. Letters Patent No. 6,968,404  
Issued: November 22, 2005  
For: OPTICAL DRIVE CONTROLLER WITH A  
HOST INTERFACE FOR DIRECT  
CONNECTION TO AN IDE/ATA DATA BUS  
Inventor: Verinsky et al.  
Our File No. 003551.P006C3

Dear Sir:

Enclosed is the Certificate of Correction (two copies) for the above-referenced patent.  
This request for correction is made under rule 322 of the Rules of Practice and 35 U.S.C.  
Section 254.

Respectfully submitted,

BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN LLP

  
Daniel M. De Vos  
Reg. No. 37,813

*Certificate  
DEC 06 2005  
of Correction*

EHT/keh  
Enclosures

DEC 6 2005

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,968,404

DATED : November 22, 2005

INVENTOR(S) : Verinsky et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 17, at line 40, delete "(36h and" and insert --(36h) and in the ATAPI Drive Select Register, and--.

In column 18, at line 47, delete "SLBHO-3" and insert --SUBHO-3--.

In column 19, at line 42, delete "LRTBSY" and insert --URTBSY--.

In column 26, at line 16, delete "(20h0.3)" and insert --(20h.3)--.

In column 26, at line 19, delete "(20h0.4)" and insert --(20h.4)--.

In column 27, at line 7, delete "(20h0.4)" and insert --(20h.4)--.

In column 27, at line 21, delete "(20h0.4)" and insert --(20h.4)--.

In column 27, at line 25, delete "(22h0.2,1,0)." and insert --(22h.2,1,0).--.

In column 27, at line 57, delete "(20h0.4)" and insert --(20h.4)--.

In column 28, at line 60, delete "PDJAG" and insert --PDIAG--.

In column 28, at line 62, delete "HJRQ" and insert --HIRQ--.

In column 30, at line 53, delete "bufkr" and insert --buffer--.

In column 32, at line 15, delete "PDJAG" and insert --PDIAG--.

---

MAILING ADDRESS OF SENDER  
BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN  
12400 Wilshire Blvd. 7th floor  
Los Angeles, CA 90025-1026

PATENT NO. 6,968,404

Certificate of Correction (PTO Form 1050)-Amended

DEC 6 2005

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 6,968,404

DATED : November 22, 2005

INVENTOR(S) : Verinsky et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In column 17, at line 40, delete "(36h and" and insert --(36h) and in the ATAPI Drive Select Register, and--.

In column 18, at line 47, delete "SLBHO-3" and insert --SUBHO-3--.

In column 19, at line 42, delete "LRTBSY" and insert --URTBSY--.

In column 26, at line 16, delete "(20h0.3)" and insert --(20h.3)--.

In column 26, at line 19, delete "(20h0.4)" and insert --(20h.4)--.

In column 27, at line 7, delete "(20h0.4)" and insert --(20h.4)--.

In column 27, at line 21, delete "(20h0.4)" and insert --(20h.4)--.

In column 27, at line 25, delete "(22h0.2,1,0)." and insert --(22h.2,1,0).--.

In column 27, at line 57, delete "(20h0.4)" and insert --(20h.4)--.

In column 28, at line 60, delete "PDJAG" and insert --PDIAG--.

In column 28, at line 62, delete "HJRQ" and insert --HIRQ--.

In column 30, at line 53, delete "bufkr" and insert --buffer--.

In column 32, at line 15, delete "PDJAG" and insert --PDIAG--.

---

MAILING ADDRESS OF SENDER

BLAKELY, SOKOLOFF, TAYLOR & ZAFMAN  
12400 Wilshire Blvd. 7th floor  
Los Angeles, CA 90025-1026

PATENT NO. 6,968,404

Certificate of Correction (PTO Form 1050)-Amended

DEC 6 2005